

Sysmetric simply accurate

Smart - Quick Start Manual

BeltColor & GraviColor Additive Dosing for Injection Molding Machines



4 - Control System Alarms



Press *Alarm Cancel* to cancel an active alarm Press *Last* to see the last alarm Press *Back* to return to Main Menu

5 – Monitor System Activity



COUNT – products counter

SET/ACT – set and actual additive weight per cycle

STOCK – material stock estimation


ADDITIVE – total weight of additive

TOTAL – total weight of main material

Press Reset to reset the counters


Press Back to return to Main Menu

2 – Enter Product Weight and Additive Percentage



Use keypad to enter the product weight and the additive percentage Press *Injection* to feed material during injections Press *Back* to return to Main Menu

3 – Enter Additive at Injection



Use keypad to enter the additive percentage to be fed during injections cycles Press *Back* to return to Product


For further assistance please refer to the User Manual or contact Sysmetric

Sysmetric Ltd

P.O.B. 1122, Afula Illit 18550, Israel

Phone: +972-4-6405857 Fax: +972-4-6405911 info@sysmetric-ltd.com www.sysmetric-ltd.com

Electrical Wiring




- 1. Connect power supply Ground, Neutral, Phase
- 2. Connect control signals from molding machine Auto Mode, Plastification, Injection
- 3. Connect alarm dry contact (optional)

Feeder Operation


Activating the GraviColor

- 1. Turn the conveyer switch to 1 the unit will load material
- 2. Hold the system switch at TEACH for 3 seconds the unit will perform a teach cycle
- 3. Set product weight and additive percentage
- 4. Turn the system switch to ON the unit will flow material according to plastification and injection signals



Activating the BeltColor

- 1. Turn the conveyer switch to 1 the unit will load material
- 2. Turn the system switch to ON the unit will perform a teach cycle
- 3. Set product weight and additive percentage
- 4. Material will start flowing according to plastification and injection inputs



System Lamps

Switch	Lamp	State
System (green)	off	system is off
	on	system is on
	flashing steadily	extruder on
	flashing alternately	teach cycle
	flashing rapidly	system alarm
Conveyer (orange)	off	conveyer is off
	on	conveyer is on
	flashing rapidly	conveyer alarm

